## **National Transportation Safety Board** Washington, DC 20594

## **Brief of Accident**

## Adopted 07/09/1990

M	IΑ	89L	_A′	19	3
	_	NIA	4	Λ1	1

File No. 1014	07/12/1989	FORT MYERS, FL	Aircraft Reg No.	N921FE	Tir	me (Local): 10:15 EDT
Engine Make/ Aircraft Da Number of Er Operating Certific Name of C Type of Flight Ope	Model: CESSNA / 208B Model: P&W / PT6A-114 mage: Substantial ngines: 1 cate(s): On-demand Air Taxi Carrier: MOUNTAIN AIR CAF eration: Non-scheduled; Dom Under: Part 135: Air Taxi & 0	RGO nestic; Cargo	Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 0
Desti Airport Pro Airport Runway Identifi Runway Length/Wid	lth (Ft): 4997 / 150 urface: Concrete			Weathd Basid Lowe Wind Tempel Obst		Veather Observation Facility Visual Conditions Ione 0.00 SM 50 / 005 Kts 1
Pilot-in-Command  Certificate(s)/Rating(s)  Airline Transport; Flight Inst Instrument Ratings  Airplane	Age: 46 tructor; Multi-engine Land; Sir	ngle-engine Land	Т	Total Las Total M	me (Hours) All Aircraft: 4 st 90 Days: 1 ake/Model: 1 ment Time: 9	94 024

THE PLT STATED THAT HE MADE A TIGHT TURN TO FINAL APCH FOR LANDING & ALLOWED THE AIRSPEED TO DISSIPATE. SUBSEQUENTLY, A HIGH SINK RATE DEVELOPED & THE ACFT LANDED HARD. DRG THE OCCURRENCE, THE MAIN GEAR PARTIALLY COLLAPSED & THE FUSELAGE WAS WRINKLED.

## Brief of Accident (Continued)

MIA89LA193

File No. 1014 07/12/1989 FORT MYERS, FL Aircraft Reg No. N921FE Time (Local): 10:15 EDT

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) AIRSPEED - INADEQUATE - PILOT IN COMMAND

2. (C) FLARE - IMPROPER - PILOT IN COMMAND

3. (C) REMEDIAL ACTION - NOT PERFORMED - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

IMPROPER FLARE BY THE PILOT FOR LANDING AND IMPROPER REMEDIAL ACTION. A CONTRIBUTING FACTOR WAS THE LACK OF AIRSPEED ON FINAL APPROACH.